



2007 Bomag BF 222

ENGINE	
Brand	Perkins
Type	403D-15 (25 Kw)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	4/5 good
Quality cooling liquid	4/5 good
Cooling liquid level	OK
Engine oil	4/5 good

ENGINE	
Engine leackages	no leakages
CONVEYOR CHAINS	
Condition of flight-chains in %	70%
Condition of the floor-plates in %	50%
Condition of sprockets in %	60%
SCREED	
Type of screed	HF from 1,40m/2,60m + n.2 extentions of 0,30m cad.
Condition of screed-plates in %	50%
Condition of tamper in %	No tamper
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %	
Overall conditions	80%
Pads	90%
Remarks	perfect conditions
BODY WORK	
Condition of the body work	80%
Condition of the paint	new paint
CABIN	
Condition of the seat	
Condition of the dashboard	70%

- **Brand:** Bomag
- **Model:** BF 222
- **Year:** 2007
- **Serial number:** 821837440013
- **Hours:** 3.000
- **Weight:** 5,1 Ton
- **Screed:** HF from 1,40m/2,60m
- **Leveling system / sensor:** n.1 longitudinal sonic
- **Optional:** n.2 extentions of 0,30m cad