



2012 Volvo 7820B

ENGINE	
Brand	Volvo
Type	D7E GEE3 (170 Kw)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK

ENGINE	
Blow by	4/5 good
Quality cooling liquid	4/5 good
Cooling liquid level	OK
Engine oil	4/5 good
Engine leackages	no leakages
CONVEYOR CHAINS	
Condition of flight-chains in %	80%
Condition of the floor-plates in %	70%
Condition of sprockets in %	70%
SCREED	
Type of screed	VB 781 (from 2.55m to 5m)
Condition of screed-plates in %	80%
Condition of tamper in %	70%
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %	
Overall conditions	70%
Traks/pads	60%
Remarks	nothing
BODY WORK	
Condition of the body work	80%
Condition of the paint	new paint
CABIN	
Condition of the seat	90%
Condition of the dashboard	80%

- **Brand:** Volvo
- **Model:** 7820B
- **Year:** 2012
- **Serial number:** 701781
- **Hours:** 6.910
- **Weight:** 18,2 ton
- **Screed:** VB 781 (from 2.55m to 5m)
- **Leveling system/sensors:** n. 2 augers sensor / n.2 sonic grade + slope