



1994 Marini P 230

ENGINE	
Brand	Deutz
Type	912 F4L
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	3/5 good
Quality cooling liquid	3/5 good
Cooling liquid level	OK
Engine oil	3/5 good

ENGINE	
Engine leackages	no leakages
CONVEYOR CHAINS	
Condition of flight-chains in %	90%
Condition of the floor-plates in %	80%
Condition of sprockets in %	90%
SCREED	
Type of screed	from 2,30m to 4,40m gas heating
Condition of screed-plates in %	50%
Condition of tamper in %	no tamper
HIDRAULICS	
Speed hydraulics functions	3/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %	
Back tyres	60%
Front tyres	60%
Remarks	brakes good
BODY WORK	
Condition of the body work	60%
Condition of the paint	original paint
CABIN	
Condition of the seat	80%
Condition of the dashboard	60%

- **Brand:** Marini
- **Model:** P 230
- **Year:** 1994
- **Serial number:** P230HH*0759*
- **Hours:** 4.100
- **Weight:** 11 Ton
- **Screed:** from 2,30m to 4,40m gas heating