



## 1988 Bitelli Volpe SF 100

ENGINE	
Brand	Deutz
<b>GENERAL</b>	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK

<b>ENGINE</b>	
Blow by	3/5 good
Quality cooling liquid	3/5 good
Cooling liquid level	OK
Engine oil	3/5 good
Engine leakages	no leakages
<b>LEVELING SYSTEM</b>	
original Moba leveling system	
<b>DRUM</b>	
Width of drum	1000 mm width / 180 mm depth
Condition of tool-holder in %	50%
Condition of teeth %	50%
<b>HIDRAULICS</b>	
Speed hydraulics functions	3/5 good
Hydraulic noise	no noise
Hydraulics leakages	no leakages
<b>CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %</b>	
Back tyres	90%
Front tyres	90%
Remarks	nothing
<b>BODY WORK</b>	
Condition of the body work	70%
<b>CABIN</b>	
Condition of the seat	70%
Condition of the dashboard	60%

- **Brand:** Bitelli
- **Model:** Volpe SF 100
- **Year:** 1988
- **Serial number:**
- **Hours:** 1.950
- **Weight:** 11 Ton
- **Drum:** 1000 mm width / 180mm depth
- **Leveling system:** no