



2000 Hamm 2320D

ENGINE	
Brand	Deutz
Type	BF 4L 1011 (66 Kw)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK

GENERAL	
Optional vibration	
ENGINE	
Blow by	4/5 good
Quality cooling liquid	4/5 good
Cooling liquid level	OK
Engine oil	4/5 good
Engine leakages	no leakages
FORWARD MOTION	
Condition of gearbox	80%
Condition of hidraulic pump	80%
CABIN	
Seat	70%
Glass	90%
General	80%
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leakages	no leakages
CONDITION OF WEAR PARTS	
Overall conditions	80%
Drum	80%
Back tyres	80%
Silent block	80%
Remarks	nothing
BODY WORK	
Condition of the body work	80%
Condition of the paint	original company coulor

- **Brand:** Hamm
- **Model:** 2320D
- **Year:** 2000
- **Hours:** 442
- **Serial number:** 44504
- **Weight:** 7,2 Ton
- **Optional:** cabin