



2010 Caterpillar CS 56

ENGINE	
Brand	Caterpillar
Type	C6.6 ACERT (108 Kw)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
Optional vibration	HT model
ENGINE	
Blow by	5/5 good
Quality cooling liquid	4/5 good
Cooling liquid level	OK
Engine oil	4/5 good

ENGINE	
Engine leakages	no leakages
FORWARD MOTION	
Condition of gearbox	80%
Condition of hidraulic pump	80%
CABIN	
Seat	50%
Glass	90%
General	80%
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leakages	no leakages
CONDITION OF WEAR PARTS	
Overall conditions	70%
Drum	70%
Back tyres	60%
Silent block	90%
Remarks	nothing
BODY WORK	
Condition of the body work	80%
Condition of the paint	new paint on front drum

- **Brand:** Caterpillar
- **Model:** CS 56
- **Year:** 2010
- **Hours:** 6.160
- **Serial number:** *CAT0CS56LFCS00519*
- **Weight:** 12,3 Ton
- **Optionals:** rops cabin