



1998 Hamm DV6.42

ENGINE	
Brand	Deutz
Type	BF4L 1011
GENERAL	
Hydraulic oil checked	YES OK

GENERAL	
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	3/5 good
Quality cooling liquid	3/5 good
Cooling liquid level	OK
Engine oil	3/5 good
Engine leakages	no leakages
DRUMS and VIBRATION	
Condition of drums in %	60%
Small/Big vibrations %	OK
Tyres/drums	n.2 drums
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leakages	no leakages
CE certificate	Yes
BODY WORK	
Condition of the body work	70%
Condition of the paint	complet original paint
CABIN	
Condition of the seat	40%
Condition of the dashboard	70%

- **Brand:** Hamm
- **Model:** DV 6.42
- **Year:** 1998
- **Serial number:** 42 417
- **Hours:** 5.200
- **Weight:** 7.8 Ton
- **Optionals:** rops cabin