



2010 Ammann AV 110X

ENGINE	
Brand	Cummins
Type	QSB 3.3-C99 (99 hp)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	5/5 good
Quality cooling liquid	4/5 good
Cooling liquid level	OK
Engine oil	4/5 good

ENGINE	
Engine leackages	no leakages
DRUMS and VIBRATION	
Condition of drums in %	front 80% — back 80%
Small/Big vibrations %	OK
Tyres/drums	n.2 drums
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CE certificate	Yes
BODY WORK	
Condition of the body work	80%
Condition of the paint	company coulor
CABIN	
Condition of the seat	90%
Condition of the dashboard	90%

- **Brand:** Ammann
- **Model:** AV 110X
- **Year:** 2010
- **Serial number:** 4102019
- **Hours:** 2.980
- **Weight:** 10,4 Ton
- **Optionals:** cabin with A/C